


EMX 9 M026



What's New?

- Enhancements
- Components



Enhancements

Enable handling of CSYS-pattern with just two instances

Avoid multiple assembly of cooling components if their owner model exists multiple times

Enable wildcard <part_refx> also for predefined components

Avoid toggling of HASCO Z10 guide bush when changing moldbase size

Set correct ordering number Parameters when changing components with UPDATE_MOLDBASE_COMPS and UPDATE_ADDITIONAL_COMPS



Components

Knarr

- 37121
- 37411
- 37666
- 37418
- 37414

Misumi

- EHS Ejector pins (LG2 dim corrected)

